

## TEST REPORT

No. : GZIN2304000067CM01\_EN

Date : 2023-05-12

Page: 1 of 4



CUSTOMER NAME: 1GLOBALSERVICE LLC  
 ADDRESS: ROOM 2004, BUILDING B1, GUANGDA WE VALLEY,  
 HEADQUARTERS NO.2 ROAD, SONGSHAN LAKE, DONGGUAN,  
 GUANGDONG, CHINA

Sample Name : Car luggage rack lock cylinder  
 Product Specification : 9340  
 Manufacturer : Xuzhou Fornd Industrial Technology Co., Ltd.  
 Material : Zinc Alloy

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

\*\*\*\*\*

SGS Ref. No. : TJIN2304000015CM01  
 Other Ref. No. : TJIN2304000648PL01  
 Date of Receipt : 2023-04-21  
 Testing Period : 2023-04-21 ~ 2023-05-12  
 Test result(s) : For further details, please refer to the following page(s)  
 (Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for  
 SGS-CSTC Standards Technical  
 Services Co., Ltd. Guangzhou  
 Branch.

*Jordan Lin*

Jordan Lin  
 Authorized signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.  
 Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)  
 Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760  
 t (86-20) 82155688 www.sgsgroup.com.cn  
 s (86-20) 82155688 sgs.china@sgs.com  
 中国·广东·广州市黄埔区开创大道1501号3栋101房 邮编: 510760

## TEST REPORT

No. : GZIN2304000067CM01\_EN

Date : 2023-05-12

Page: 2 of 4

### Summary of test result

The sample(s) submitted complied with Durability test which provided by applicant. See the next page for details.

### Sample information

Name: Car luggage rack lock cylinder

Model: 9340

## TEST REPORT

No. : GZIN2304000067CM01\_EN

Date : 2023-05-12

Page: 3 of 4

Clause	Test items	Test requirement	Test method and test condition	Test result	Verdict
/	Durability	After 100 000 cycles test, function normally	Insert the key, and rotate it to 180°, then rotate to 0°, at last pull the key out.	After 100 000 cycles test, function normally.	PASS



## TEST REPORT

No. : GZIN2304000067CM01\_EN

Date : 2023-05-12

Page: 4 of 4

Original Sample Photo:



\*\*\*\*\*End of report\*\*\*\*\*